



Photo 1: Accident Airplane / Left wing tip and main wing spar – (Photo provided by FAA)



Photo 2: Accident Airplane / Close-up of left wing and main wing spar – (Photo provided by FAA)



Photo 3: Electrical Box / Moved off the foundation and yellow paint transfer – (Photo provided by FAA)



Photo 4: Damaged winglet / electrical box – (Photo provided by FAA)



Photo 5: Damaged aileron - (Photo provided by FAA)