



Photo 1 - Helicopter at Accident Site (Courtesy of Operator)



Photo 2 – Front View of Helicopter (Courtesy of Operator)



Photo 3 – Tail Rotor with Tree Debris (Courtesy of FAA)