

CEN23LA118

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of the Pilot)



Photograph 2 - Accident Site (Courtesy of the Pilot)



Photograph 3 - Vertical Stabilizer (Courtesy of the Federal Aviation Administration)



Photograph 4 - Fuselage (Courtesy of the Federal Aviation Administration)



Photograph 5 - Bulkhead (Courtesy of the Federal Aviation Administration)



Photograph 6 - Left Cabin Stay Rib (Courtesy of the Federal Aviation Administration)