

Carburetor Icing Probability Graph – CEN23LA145

Airplane: N56793, Piper PA-32-260

Engine: Lycoming Engines O-540-E4B5

Fuel: 100LL

Accident Date: 03/29/2023

Accident Location: Lincoln, Illinois

Accident Time: 1915 Local Time

METAR: KAAA 300015Z [1915 Local Time] AUTO
03005KT 10SM CLR 07/M02 A3023 RMK AO2
T00721018

Celsius to Fahrenheit Conversions:

Temperature, 7° C = 44.6° F

Dew Point, -2° C = 28.4° F

Source: Federal Aviation Administration

Special Airworthiness Information Bulletin CE-09-35

Carburetor Icing Prevention

