



**Photo 1 – Aircraft on Side of RWY18 (EVV Fire/Safety Dept)**



**Photo 2 - View of R/H Lower Wing (EVV Fire/Safety Dept)**



**Photo 3 – View of Damage to R/H Aileron (EVV Fire/Safety Dept)**



**Photo 4 – Close up view of R/H Aileron Leading Edge (EVV Fire/Safety Dept)**