



Photo 1 – Accident Aircraft (Photo provided by FAA)



Photo 2 – Upper wing and cowling (Photo provided by FAA)



Photo 3 – L/H Lower Wing (Photo provided by FAA)



Photo 4 – Empennage R/H Side (Photo provided by FAA)