

N60860

PRECISION PROPELLER



SERVICE
INC.

Aircraft Propeller Log

Description of Inspections and Repairs

the FAA Repair Station or the mechanic.

[illegible]

PHOTO

Description of Inspections and Repairs
ALL DATA must be endorsed with the name, rating and certificate number of the FAA Repair Station or the mechanic.

Services, LLC

Augusta, KS 67010



DATE

Date: 23 Apr 2021

Aircraft: N60860 Tach: 1839.0

Checked magneto to engine timing.

Checked and cleaned fuel screens.

Run-up satisfactory. I certify this Engine/prop was inspected LAW an Annual/100 Hour inspection and determined satisfactory for return to service. Nothing follows.

TSOH: 451.5

Engine/Prop

Compression check #1) 72, #2) 72, #3) 70, #4) 75 all over 80. Clean and gap plugs.
Inspected exhaust system. Replaced crank seal with new P/N 07-12764. Cleaned engine.

SIGNATURE

Lee A. Cross