



Photo 1 – View of thermal damage to the fuselage and left wing (Photo provided by FAA)



Photo 2 – View of thermal damage to the fuselage, and retracted landing gear (Photo provided by FAA)