



Photo 1 – Subject Airplane Post-Accident (Provided by KMKC Airport Operations)



Photo 2 – Impact Damaged Left Wing (Provided by KMKC Airport Operations)



Photo 3 – Damaged Right Wing (Provided by KMKC Airport Operations)