



Photo 1 – Left side view of the helicopter at the accident site (courtesy of the Federal Aviation Administration).



Photo 2 – Right side view of the helicopter at the accident site (courtesy of the Federal Aviation Administration).



Photo 3 – View of the tail rotor system at the accident site (courtesy of the Federal Aviation Administration).



Photo 4 – View of the main rotor blades at the accident site (courtesy of the Federal Aviation Administration).



Photo 5 – View of the tail rotor system at the operator’s facility (courtesy of the Federal Aviation Administration).



Photo 6 – View of the main rotor blades at the operator’s facility (courtesy of the Federal Aviation Administration).