



Photo 1 – Accident Airplane (Courtesy of Vermilion Parish Sheriff's Office)



Photo 2 - Airplane in Field (Courtesy of Vermilion Parish Sheriff's Office)



Photo 3 - Engine Fractured from Airplane (Courtesy of Vermilion Parish Sheriff's Office)



Photo 4 – Airplane in Field (Courtesy of Vermilion Parish Sheriff's Office)



1977 Ag Cat G-164B,
N6699Q, 64-gallon fuel,
R985 engine, Airframe
12,000+ hours, Engine

1,300hrs+, Engine Compression all
cylinders 70/80 psi, 25"

Swathmaster spreader, Factory spray
system, Propeller Hamilton Standard
2D30 / AG100-2, Prop balance in
2021, Satloc GPS, \$45,000, Contact



Photo 5 - Exemplar Airplane (Courtesy of AgAir Update)