

CEN23LA205

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Wreckage Right Side View (Courtesy of FAA)



Photograph 2 - Airplane Wreckage Left Side View (Courtesy of FAA)