

CEN23LA206

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane Overview (Courtesy of Federal Aviation Administration)



Photograph 2 - Damage to Vertical Stabilizer & Rudder (Courtesy of FAA)



Photograph 3 - Fuel Selector as Found (Courtesy of NTSB IIC)