



Photo 1 – Subject Airplane (FAA)



Photo 2 - Damaged Rudder of Accident Airplane (FAA)



Photo 3 – Loose Tailwheel Spring Attachment Hardware (FAA)