



Photo 1 – Left view of airplane (Photo Provided by FAA)



Photo 2 – Substantially damaged left wing and aileron (Photo Provided by FAA)



Photo 3 -Substantially damaged left aileron (Photo Provided by FAA)