


CEN23LA241

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane on side of runway (Courtesy of operator)



Photograph 2 - Right hand wing substantial damage (Courtesy of operator)



Photograph 3 - Damaged landing gear (Courtesy of operator)