

CEN23LA243

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of Texas Division of Emergency Management)



Photograph 2 - Right Wing Damage (Courtesy of Texas Division of Emergency Management)



Photograph 3 - Right Wing Damage (Courtesy of Texas Division of Emergency Management)



Photograph 4 - Fuel Selectors (Courtesy of Texas Division of Emergency Management)



Photograph 5 - Cockpit (Courtesy of Texas Division of Emergency Management)