



Photo 1 – Front view of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 2 – Left side view of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 3 – Rear view of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 4 – Right side view of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 5 – Front view of the airplane after it was recovered from the accident site (courtesy of the Federal Aviation Administration).



Photo 6 – View of the substantial damage sustained to the fuselage (courtesy of the Federal Aviation Administration).



Photo 7 – View of the substantial damage sustained to the fuselage (courtesy of the Federal Aviation Administration).



Photo 8 – View of the substantial damage sustained to the left wing (courtesy of the Federal Aviation Administration).