

CEN23LA250

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right side view of the airplane at the accident site, resting partially inside of a vehicle parked on a residential street (courtesy of the Wisconsin State Journal)



Photograph 2 - Right side view of the airplane at the accident site, resting partially inside of a vehicle parked on a residential street (courtesy of the Wisconsin State Journal)