

Repairs and Alterations
 ing and Certificate Number of
 ages for other specific entries.)

E. REPAIRED RT
 BRIC (SEE 337 DATED
 OVE WHEEL & BRAKE
 E/ 29-10 10C BRAKE
 IUM WHEEL ASSY.
 10). CHECKED BIT.
 225. LUBED FLIGHT
 11 AD'S. COMPILED
 2 RI BY INSPECTION.
 ANCE. PERFORMED
 K OF BRAKES &
 FY THAT THIS AIRCRAFT
 IN ACCORDANCE WITH
 N & WAS DETERMINED
 CONDITION.

IL ABP [REDACTED] IA
 8-12-2020

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				
5-21-23	4837	4	SMR 34 hrs	Perform Corrosion inspection on this aircraft
6-1-23	6165			Compass 1. 7/80 2. 7/80 3. 7/80 4. 7/80
SMR 34.0				Inspected engine - engine inspected this aircraft. Checked Operation of lights, flight control. C/w DMR 91.2021 on C/w. Installed new EAT Battery. Inspected Brake reservoir. Checked XP testing. C/w AD 2000-25-02 R4 by inspection. Declared this aircraft is airworthy for return to Service on this date, time.
				[REDACTED] 122P [REDACTED] IA

me, Rating and Certificate Number of
the back pages for other specific entries.)

CHECKED WHEELS &
3-IT wing tip &
2000-25-02 R1 Both
AD'S. INSTALLED NEW
ERY. "SEE 337" I
ET HAS BEEN INSPECTED
AN ANNUAL INSPECTION
A TO BE IN AIRWORTHY

L A2P [REDACTED] TA
6-25-2018

90, SN: 42486-1-12

YE: N80461 Champion 7EC SN: 7EC743
1/15/2020 Tach: 4803.0 Total: 6130.6

Reinstalled engine (C-90, 42486-1-12) after repair by G&N Aircraft, CRS MW2R020L, wo# 73755, dated 10/28/2019. Lubricated flight controls. Serviced tires. Inspected ELT in accordance with FAR 91.207d. ELT batteries due December 2025. Serviced brake reservoirs. Replaced air filter element (BA-4108.) See AD Compliance Record and Recurring Listings for complete status of applicable airworthiness directives. See Beaver Aviation Inc. "Aircraft Inspection Report" for details of this inspection.

I certify this aircraft has been inspected in accordance with and annual inspection and was determined to be in airworthy condition.

Eric Nelson AP [redacted] IA [redacted]
Beaver Aviation Inc. [redacted] uneau WI 53039 [redacted]

YEAR: 2018 DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries)
				Pulleys with new. Checked wheels & brakes. Painted right wing tip & complied with AD 2000-25-02 R1 both wings. Checked all AD's. Installed new Odyssey sealed battery. "SEE 337" I certify this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. MARK HENRY UNERTL A2P [REDACTED] IA [REDACTED] 6-25-2018 Removed engine (C-90, SN: 42486-1-12) for repair. [REDACTED] AP [REDACTED]
4-15-19	4803.0			

YE	DESCRIPTION	TACH	TOTAL
N80461	Champion 7E		
1/15/2020	Tach: 4803		
DA	Reinstalled engine (C-90, 42 dated 10/28/2019. Lubricated ELT batteries due Decem See AD Compliance Re See Beaver Aviation I certify this aircraft is airworthy condition Eric Nelson AP Beaver Aviation		