

CEN23LA288

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damaged Wing (Courtesy of FAA)