

CEN23LA344

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane with substantial damage to left wing (Courtesy of Federal Aviation Administration (FAA))



Photograph 2 - Underside of airplane with substantial damage to the fuselage (Courtesy of FAA)