

CEN23LA356

INVESTIGATION PHOTOGRAPHS



Photograph 1 - R/H View of Damaged Fuselage (Courtesy of FAA)



Photograph 2 - Interior View of Cockpit (Courtesy of FAA)



Photograph 3 - Front View of Airplane (Courtesy of FAA)