

CEN23LA358

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right view of helicopter with deformation noted to its skids (Courtesy of FAA)



Photograph 2 - Rear view of helicopter with deformation noted to its skids (Courtesy of FAA)



Photograph 3 - deformation to the skids and fuselage tubular structure (Courtesy of FAA)