

CEN23LA384

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Dented Vertical Stabilizer Leading Edge (Courtesy of Purdue Aviation)