

CEN23LA386

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Gyroplane with substantial damage (Courtesy of Federal Aviation Administration)



Photograph 2 - Gyroplane Front View (Federal Aviation Administration)