

CEN23LA388

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left horizontal stabilizer and elevator (Courtesy of Wichita Airport Police and Fire Division)



Photograph 2 - Left side of fuselage (Courtesy of Wichita Airport Police and Fire Division)




Photograph 3 - Right wing (Courtesy of Wichita Airport Police and Fire Division)



Photograph 4 - Right wing (Courtesy of Wichita Airport Police and Fire Division)



Photograph 5 - Left wing (Courtesy of Wichita Airport Police and Fire Division)



Photograph 6 - Engine during examination (Courtesy of FAA)