

CEN23LA408

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right side of airplane at accident site. (Courtesy of FAA)



Photograph 2 - Front of airplane at accident site. (Courtesy of FAA)



Photograph 3 - Left side of airplane at accident site. (Courtesy of FAA)