

CEN23LA413

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the accident site and the aircraft (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the accident site and the aircraft (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the accident site and the aircraft (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the front of the aircraft (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the cockpit (courtesy of the Federal Aviation Administration)



Photograph 6 - View of the rear seat (courtesy of the Federal Aviation Administration)



Photograph 7 - View of the front seat and the throttle (courtesy of the Federal Aviation Administration)