


CEN23LA421

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damaged Upper and Lower Firewall (Courtesy of FAA)



Photograph 2 - Damaged Upper and Lower Firewall (Courtesy of FAA)