


CEN24FA021

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wreckage Overview



Photograph 2 - Patched Wires



Photograph 3 - Wing Skin



Photograph 4 - Left Wing Reconstruction (Courtesy of Air Tractor)