

CEN24FA024

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at accident site as found (NTSB Photo)



Photograph 2 - Airplane during removal from lake (NTSB Photo)



Photograph 3 - Aft fuselage during examination (NTSB Photo)



Photograph 4 - Fuselage during examination (NTSB Photo)



Photograph 5 - Forward Fuselage during examination (NTSB Photo)



Photograph 6 - Right side view of wreckage (NTSB Photo)



Photograph 7 - Engine during examination (NTSB Photo)