

CEN24FA028

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of McCook Police Department)



Photograph 2 - Wreckage Overview (Courtesy of McCook Police Department)



Photograph 3 - Engine Controls (Courtesy of McCook Police Department)



Photograph 4 - Engine Control Linkage