

CEN24FA073

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Accident Site (NTSB ICC)**



**Photograph 2 - Tree Line (NTSB IIC)**



**Photograph 3 - Wreckage Path (NTSB IIC)**



**Photograph 4 - Wreckage Path (NTSB IIC)**



**Photograph 5 - Wreckage Path (NTSB IIC)**



**Photograph 6 - Wreckage Path (NTSB IIC)**



**Photograph 7 - Driveway Deck Lights (NTSB IIC)**



**Photograph 8 - Runway Deck Lights (NTSB IIC)**