


CEN24FA089

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Ground Scars



Photograph 2 - Blade strikes



Photograph 3 - Right propeller blade in bush



Photograph 4 - Sheared tree limb



Photograph 5 - Main wreckage



Photograph 6 - Landing gear



Photograph 7 - Right engine



Photograph 8 - Left engine and left propeller



Photograph 9 - Left propeller