

CEN24FA094

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage



Photograph 2 - Main Rotor Mast & Transmission



Photograph 3 - Tail Rotor Section



Photograph 4 - Red Blade (Courtesy of Bell Helicopters)



Photograph 5 - White Blade



Photograph 6 - Main Rotor Mast Hub



Photograph 7 - Main Rotor Mast Nut