

CEN24FA101

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane Overview



Photograph 2 - Separated Outboard Left Wing



Photograph 3 - Wire Strike Witness Mark Aft Spar



Photograph 4 - Tower Impact Point on Left Wing Tip Leading Edge



Photograph 5 - Left Wing Impact Witness Marks on Tower Mast