

CEN24FA148

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (NTSB photo)



Photograph 2 - Accident site (NTSB photo)



Photograph 3 - Aft fuselage / empennage (NTSB photo)



Photograph 4 - Firewall/instrument panel/engine (NTSB photo)



Photograph 5 - Wing / aft fuselage / empennage (NTSB photo)



Photograph 6 - Engine / firewall / instrument panel (NTSB photo)



Photograph 7 - Instrument panel / firewall / engine (NTSB photo)



Photograph 8 - Engine (NTSB photo)



Photograph 9 - Engine (NTSB photo)