

CEN24FA167

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the helicopter at the airport just prior to the accident (courtesy of a witness)



Photograph 2 - View of the helicopter at the airport just prior to the accident (courtesy of a witness)



Photograph 3 - View of the helicopter at the airport just prior to the accident (courtesy of a witness)



Photograph 4 - View of the wreckage in front of a house



Photograph 5 - View of the wreckage in front of a house



Photograph 6 - View of the wreckage in front of a house



Photograph 7 - View of the engine at the accident site



Photograph 8 - View of various golf balls at the accident site



Photograph 9 - View of the main rotor blade remnants during the airframe examination at the accident site



Photograph 10 - View of the engine during the engine examination at the accident site



Photograph 11 - View of the pilot's fuel container at his hangar at the airport



Photograph 12 - View of the pilot's fuel funnel at his hangar at the airport