

CEN24FA179

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (NTSB Photo)



Photograph 2 - Black witness marks right aft fuselage (NTSB Photo)