

CEN24FA218

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane left side




Photograph 2 - Accident airplane right side



Photograph 3 - Accident airplane front view



Photograph 4 - Cabin and instrument panel



Photograph 5 - Ignition and master switch



Photograph 6 - Fuel selector valve on both



Photograph 7 - Throttle and mixture controls




Photograph 8 - Propeller




Photograph 9 - Fuel obtained from left wing fuel tank



Photograph 10 - Fuel obtained from right wing fuel tank



Photograph 11. Bottom of engine driven fuel pump



Photograph 12. Top of engine driven fuel pump