

CEN24FA220

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (NTSB photo)



Photograph 2 - Airplane at accident site (NTSB Photo)



Photograph 3 - Airplane at accident site (NTSB photo)



Photograph 4 - Right wing at accident site (NTSB photo)



Photograph 5 - Empennage (NTSB photo)



Photograph 6 - Empennage (NTSB photo)



Photograph 7 - Propeller at accident site (NTSB photo)



Photograph 8 - Propeller (NTSB photo)



Photograph 9 - Tree strikes (NTSB photo)