

CEN24FA243

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane (Courtesy of Jamie Treat)



Photograph 2 -Airplane Cockpit Before Accident (Courtesy of Flying Magazine)



Photograph 3 - Right Wing Tips Ground Scar & Forward Fuselage



Photograph 4 - Debris Field

2024
Date to From Landing Time
6:30 LHT PHG 851.5
1:45 CDT 4:15 CDT 2.5 854.0
33.3 remain, 26.2 used did not
6/30 PHG fuel
5:10

Photograph 5 - Accident Flight Log



Photograph 6 - Accident Airplane Data Plate