


CEN24FA278

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial view of accident site (Courtesy of NTSB)



Photograph 2 - Aerial view of accident site (Courtesy of NTSB)



Photograph 3 - Front of airplane (Courtesy of NTSB)



Photograph 4 - Front of airplane (Courtesy of NTSB)



Photograph 5 - Rear of airplane (Courtesy of NTSB)



Photograph 6 - Engine and propeller (Courtesy of NTSB)



Photograph 7 - Front of airplane (Courtesy of NTSB)



Photograph 8 - Engine and propeller (Courtesy of Air Tractor)