

CEN24FA326

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site Overview



Photograph 2 - Fuselage and Empennage



Photograph 3 - Forward Fuselage, Cockpit, and Engine