



Photo 1 – View of Aircraft with Left Wing Damaged, Photo Courtesy of Airport Operations



Photo 2 – Ground Equipment that Aircraft Impacted during Landing, Photo Courtesy of Airport Operations