

[CEN24LA029]

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane (Courtesy of FAA)



Photograph 2 - Lower right wing damage (Courtesy of FAA)



Photograph 3 - Upper right wing and aileron damage (Courtesy of FAA)