

CEN24LA032

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Overview (Courtesy of Federal Aviation Administration)



Photograph 2 - Left Wing Damage (Courtesy of Federal Aviation Administration)



Photograph 3 - Right Wing Damage (Courtesy of Federal Aviation Administration)