



Photo 1 – View of the airplane against a hangar door (courtesy of the pilot).



Photo 2 – View of the propeller against a hangar door (courtesy of the pilot).



Photo 3 – View of the substantial damage sustained to the right wing (courtesy of the pilot).



Photo 4 – View of the substantial damage sustained to the right wing (courtesy of the pilot).