

CEN24LA036


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Wing (Courtesy of FAA)



Photograph 2 - Rear View of the Airplane (Courtesy of FAA)



Photograph 3 - Number 4 Intake and Exhaust Valves (Courtesy of Lycoming)



Photograph 4 - View of Cylinder Number 4 Pushrod (Courtesy of Lycoming)



Photograph 5 - "C" Stamp on Number 4 Cylinder (Courtesy of Lycoming)